

Notes:

The conduit between the infield platforms 2 and 3is blocked.There was a previously unused conduit between the infield and DaisySt. platforms 3. This platform was cracked. Adirect burial 12-3 cable was run through this cracked conduit to supply the power to the infield platform3 outlet. This outlet will share the circuit with the flood light circuit on the Daisy St side.

The infield Blue Light box must be moved from platform 3 to Platform 2, where the infield blue light is mounted because there is no cable between platforms 2 and 3.

New Hope Valley Railway
N.C. Railroad Museum & East Carolina Chapter NRHS

Platform Electrical 2023
07/06/23

Platform Electrical 22
2/28/23

Drawn by: Ted Dunn
Approved by: